age



Docket No.: SON-2778

ATTN: CORRECTIONS BRANCH

(PATENT)

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.

6,801,074 B2

Inventor:

Tetsumasa MEGURO

Patented:

October 5, 2004

For:

**CLOCK SWITCHING CIRCUIT** 

### REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate DEC 1 5 2004

of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued in connection with the above-identified patent. It appears that a mistake(s) was recorded through the fault of the Patent and Trademark Office in the printing of the patent as clearly disclosed by the records of the Office within the meaning of 35 USC § 254. Accordingly, two copies of the special Certificate of Correction are attached hereto. It is believed that the error(s) noted is an error(s) of consequence involving claim language and thus warrants the granting of a Certificate of Correction. It is believed that the error(s) were made on the part of the Office and that no government fee is required.

Should any costs be incurred, please consider this authorization to charge Deposit Account No. 18-0013.

Dated: December 13, 2004

RADER, FISHMAN & GRAUER PLLC Suite 501, Lion Building 1233 20<sup>th</sup> Street, N.W. Washington, D.C. 20036 (202) 955-3750 Respectfully submitted,

Ronald P. Karlanen Reg. No. 24,104

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Patent No.

6,801,074 B2

Dated:

October 5, 2004

Inventor (s):

Tetsumasa MEGURO

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 12

Line 37, "delay clock" should read - - delays clock - - .

#### MAILING ADDRESS OF SENDER:

Customer No. 23353

## Rader, Fishman & Grauer PLLC

1233 20<sup>th</sup> Street, NW Suite 501 Washington, DC 20036

Patent No. US 6,801,074 B2

FORM PTO 1050 (REV. 3-82) SON-2778

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Patent No.

6,801,074 B2

Dated:

October 5, 2004

Inventor (s):

Tetsumasa MEGURO

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### Column 12

Line 37, "delay clock" should read - - delays clock - - .

#### MAILING ADDRESS OF SENDER:

Customer No. 23353

## Rader, Fishman & Grauer PLLC

1233 20<sup>th</sup> Street, NW-Suite 501 Washington, DC 20036

Patent No. US 6,801,074 B2

FORM PTO 1050 (REV. 3-82) SON-2778